



Construction Progress Photo Report - August 2012 Hemet High Modernization & Expansion



FACILITIES & PLANNING DEPARTMENT

Theater Building "A"


July 10, 2012: Carpet, flooring and seats are nearing completion.



Balfour Beatty
Construction

Theater Building "A"


Aug. 1, 2012: Orchestra Pit Cover has been installed.



Balfour Beatty
Construction

Theater Building "A"


July 13, 2012: The aisle way lighting and black box theatrical dimming system is complete.



Balfour Beatty
Construction

Theater Building "A"

Aug. 1, 2012: Light & Sound Booth



Balfour Beatty
Construction

Theater Building "A"


July 13, 2012: Stage lighting is complete and tested.



Balfour Beatty
Construction

Theater Building "A"

July 20, 2012: Theater rigging line sets as viewed from the loading bridge.



Balfour Beatty
Construction

Theater Building "A"

Aug. 1, 2012: Stage curtain installed. The make up light fixtures are being installed at the dressing rooms.



Balfour Beatty
Construction

Theater Building "A"

July 11, 2012: (L)-The tinted concrete sealer has been installed at the dressing rooms & vestibule. (R)-Wheelchair lift installation is beginning at the light & sound booth.



Balfour Beatty
Construction

Theater Building "A"

Aug. 1, 2012: Wheel chair lifts have been installed and tested.



Balfour Beatty
Construction

Theater Building "A"

July 13, 2012: Lobby display cases have been completed.



Balfour Beatty
Construction

Theater Building "A"

Aug. 1, 2012: Completed lobby bathrooms.



Balfour Beatty
Construction

Theater Building "A"


Aug. 1, 2012: Front Entry gate.



Balfour Beatty
Construction

Theater Building "A"

Aug. 1, 2012: Site work along Stetson Avenue



Balfour Beatty
Construction

Theater Building "A"

Aug. 1, 2012



Balfour Beatty
Construction

Security Cameras – CCTV project

ATTENDANCE WINDOW



BUSINESS HALLWAY



CATV Installation



41 LCD Projector Installation



Summer Remodel

July 3, 2012: (L)- Old theater concrete floor has been sealed.
(R)-Drywall installation in progress at a remodeled classroom.



Balfour Beatty
Construction

Summer Remodel

July 20, 2012: The remodeled classrooms are nearly complete.



Balfour Beatty
Construction

Summer Remodel

Old Science Buildings

LAB EQUIPMENT REMOVED



NEW PAINT, CARPET, AND FURNITURE



Solar Panel Installation

BAUTISTA CREEK ES



CAWSTON ES



Solar Panel Installation

DARTMOUTH MS



DIAMOND VALLEY MS



Solar Panel Installation

FRUITVALE ES



HARMONY ES



Solar Panel Installation

HEMET HS



JACOB WIENS ES



Solar Panel Installation

MCSWEENY ES



RANCHO VIEJO MS



Solar Panel Installation

TAHQUITZ HS



VALLE VISTA ES



Solar Panel Installation

WEST VALLEY HS



WINCHESTER ES



Nutrition Center Freezer Expansion

ENCLOSURE ALMOST COMPLETE



Bautista ES Office Gates



Diamond Valley MS Office Gates



McSweeney ES Office Gates



Valle Vista ES Office Gates

